


967104 - R8 SDMS

503146

		POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION		REGION VIII	SITE NUMBER UTD981542145
NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.					
A. SITE NAME Uintah Drums		B. STREET (or other identifier) 1336 East 335 South			
C. CITY Vernal		D. STATE UT	E. ZIP CODE 84078	F. COUNTY NAME Uintah	
G. OWNER/OPERATOR (if known)					
1. NAME Jack Durban; Crown Mud, Inc.				2. TELEPHONE NUMBER 801-789-5137	
H. TYPE OF OWNERSHIP (if known) <input type="checkbox"/> 1. FEDERAL <input type="checkbox"/> 2. STATE <input type="checkbox"/> 3. COUNTY <input type="checkbox"/> 4. MUNICIPAL <input checked="" type="checkbox"/> 5. PRIVATE <input type="checkbox"/> 6. UNKNOWN					
I. SITE DESCRIPTION Property is owned by Pease Bros., Inc. (R. W. Pease, 646 East 200 North, Vernal), which is now out of business. Part of the site is leased to Jack Durban, who owns Crown Mud, Inc. On this site Durban has stored 36 55-gallon drums and 15 5-gallon containers. About one-third of the drums are leaking; five have corrosive warning labels and some have a yellow poly liner that is falling apart and contain a yellow substance. Other drums appear to contain a type of polymer. The 5-gallon containers have physiological and toxic warning labels.					
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) Lowell Card, Uintah Basin District Health Department 801-781-0700				K. DATE IDENTIFIED (mo., day, & yr.) 5/12/86	
L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM The drums appear to have been on site for years. The area is fenced but not locked. Some of the leaking material had run off the site after a rain and had formed a pool or pools. Mr. Card reported that there could be a problem with children playing in material that had washed off the property, depending on the nature of the materials. He has placed a berm around the leaking drums to temporarily contain the leaking material on-site. The contents of the drums and containers are unknown and could pose an immediate or potential hazard to residents in the area.					
M. PREPARER INFORMATION					
1. NAME Laurie L. Goldner		2. TELEPHONE NUMBER 801-538-6170		3. DATE (mo., day, & yr.) 5/21/86	

